

Test Report

Number: GZHH00641273

Applicant: DINO DECKING LTD.
UNIT 1 WETHERAL CLOSE, HINDLEY GREEN,
WN2 4HS

Date: May 13, 2026

Sample Description:

One (1) submitted sample said to be :

Item Name : **Dino Slatted Composite Cladding**
Item No. : **EX-CSC-*-4M**
Manufacturer : Huangshan Huasu New Material Science & Technology Co., Ltd
Date Sample Received : Apr 10, 2026
Testing Period : Apr 10, 2026 to May 06, 2026



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Page 1 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District,
Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road,
Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、
601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Conclusion:

Tested sample
Submitted sample
(Vertical)

Test item
Fire Classification Test on Dino Slatted Composite Cladding
- As per EN 13501-1: 2018


Result
See test
conducted

Submitted sample
(Horizontal)

Fire Classification Test on Dino Slatted Composite Cladding
- As per EN 13501-1: 2018

See test
conducted

Authorized by:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch, Hardlines



Victor T.J. Wang
General Manager



Should you have any query on this report, please click the link below:
https://verifyindex.intertek.com.cn/home/index?id=hl_report_verify



Page 2 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

1 Fire Classification Test on Dino Slatted Composite Cladding

As per the client's requirement, the tested sample was subjected to the following tests.

Sample description: Dino Slatted Composite Cladding

Sample mounting direction: Vertical

Initial inspection: Not any damage was found

Executive summary:

No.	Test item			Test method	Standard's requirement		Test result	Conclusion
1	Fire growth rate index ($FIGRA_{0.4MJ}$)			EN 13823-2020+A1:2022	D	$\leq 750 \text{ W/s}$	581W/s	Pass
2	Lateral flame spread (LFS)			EN 13823-2020+A1:2022		--	< edge of specimen	--
3	Total heat release within 600 s (THR_{600s})			EN 13823-2020+A1:2022		--	65.3 MJ	--
4	Flammability	Surface flame attack (Exposure = 30 s)	Flame spread within 60s	EN ISO 11925-2-2020		$\leq 150 \text{ mm}$	$\leq 150 \text{ mm}$	Pass
5	Smoke production	Smoke growth rate ($SMOGRA$)		EN 13823-2020+A1:2022	s1	$SMOGRA \leq 30 \text{ m}^2/\text{s}^2$ $TSP_{600s} \leq 50 \text{ m}^2$	43.9 m^2/s^2	Class: s3
		s2	$SMOGRA \leq 180 \text{ m}^2/\text{s}^2$ $TSP_{600s} \leq 200 \text{ m}^2$		482.7 m^2			
		Total smoke production within 600 s (TSP_{600s})				s3	Not s1 or s2	



Page 3 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

No.	Test item	Test method	Standard's requirement		Test result	Conclusion
6	Flaming droplets/particles	EN 13823-2020+A1:2022	d0	No flaming droplets/particles within 600 s	No flaming droplets /particles	Class: d0
			d1	No flaming droplets/particles persisting longer than 10 s within 600 s		
			d2	Not d0 or d1		
Conclusion	EN 13501-1:2018 Fire classification of construction products and building elements - Part 1: Classification using data from reaction to fire tests : D—s3, d0					
Remark	1. Test sample is installed on the substrate by screw (test substrates is calcium silicate board, the density of 900 kg/m³ and thickness of 10mm). 2. The test results relate to the behavior of the test specimens of a product under the particular conditions of the test; they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use. 3. This classification report does not represent type approval or certification of the product. The test laboratory has, therefore, play no part in sampling the product for the test, although it holds appropriate references to the manufacturer's factory production control that is aimed to be relevant to the samples tested and that will provide for their traceability.					



Page 4 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com


Test Report

Number: GZHH00641273

Tests Conducted

Photo for reference

Before the test long wing	Before the test short wing
After testing long wing	After testing short wing



Page 5 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

Annex A

Classes of reaction to fire performance for construction products excluding floorings and linear pipe thermal insulation products

Class	Test method(s)		Classification criteria	Additional classification
A1	EN ISO 1182 ^a and		$\Delta T \leq 30^{\circ}\text{C}$, and $\Delta m \leq 50\%$, and $t_f = 0$ (i.e. no sustained flaming)	-
	EN ISO 1716		$PCS \leq 2.0\text{MJ/kg}$ ^a and $PCS \leq 2.0\text{MJ/kg}$ ^{b c} and $PCS \leq 1.4\text{MJ/m}^2$ ^d and $PCS \leq 2.0\text{MJ/kg}$ ^e	-
A2	EN ISO 1182 ^a or	and	$\Delta T \leq 50^{\circ}\text{C}$, and $\Delta m \leq 50\%$, and $t_f \leq 20\text{ s}$	-
	EN ISO 1716		$PCS \leq 3.0\text{MJ/kg}$ ^a and $PCS \leq 4.0\text{MJ/m}^2$ ^b and $PCS \leq 4.0\text{MJ/m}^2$ ^d and $PCS \leq 3.0\text{MJ/kg}$ ^e	-
	EN 13823		$FIGRA_{0.2\text{MJ}} \leq 120\text{W/s}$ and $LFS < \text{edge of specimen}$ and $THR_{600\text{s}} \leq 7.5\text{MJ}$	Smoke production ^f and Flaming droplets/particles ^g



Test Report

Number: GZHH00641273

Tests Conducted

Class	Test method(s)	Classification criteria	Additional classification
B	EN 13823 and	$FIGRA_{0.2MJ} \leq 120W/s$ and $LFS < \text{edge of specimen}$ and $THR_{600s} \leq 7.5MJ$	Smoke production ^f and Flaming droplets/particles ^g
	EN ISO 11925-2 ⁱ Exposure =30s	$F s \leq 150 \text{ mm within } 60 \text{ s}$	
C	EN 13823 and	$FIGRA_{0.4MJ} \leq 250W/s$ and $LFS < \text{edge of specimen}$ and $THR_{600s} \leq 15MJ$	Smoke production ^f and Flaming droplets/particles ^g
	EN ISO 11925-2 ⁱ Exposure=30s	$Fs \leq 150mm \text{ within } 60 \text{ s}$	
D	EN 13823 and	$FIGRA_{0.4MJ} \leq 750W/s$	Smoke production ^f and Flaming droplets/particles ^g
	EN ISO 11925-2 ⁱ Exposure=30s	$Fs \leq 150mm \text{ within } 60 \text{ s}$	
E	EN ISO 11925-2 ⁱ Exposure =15s	$Fs \leq 150mm \text{ within } 20 \text{ s}$	flaming droplets/particles ^h
F	No performance determined		



Test Report

Number: GZHH00641273

Tests Conducted

Class	Test method(s)	Classification criteria	Additional classification
	^a For homogeneous products and substantial components of non-homogeneous products. ^b For any external non-substantial component of non-homogeneous products. ^c Alternatively, any external non-substantial component having a $PCS \leq 2,0 \text{ MJ/m}^2$, provided that the product satisfies the following criteria of EN 13823: $FIGRA \leq 20 \text{ W/s}$, and $LFS < \text{edge of specimen}$, and $THR_{600s} \leq 4,0 \text{ MJ}$, and $s1$, and $d0$. ^d For any internal non-substantial component of non-homogeneous products. ^e For the product as a whole. ^f $s1 = SMOGRA \leq 30 \text{ m}^2/\text{s}^2$ and $TSP 600s \leq 50 \text{ m}^2/\text{s}^2$; $s2 = SMOGRA \leq 180 \text{ m}^2/\text{s}^2$ and $TSP 600s \leq 200 \text{ m}^2/\text{s}^2$; $s3 = \text{not } s1 \text{ or } s2$ ^g $d0 = \text{No flaming droplets/ particles in EN 13823 within 600 s}$; $d1 = \text{no flaming droplets/ particles persisting longer than 10 s in EN 13823 within 600 s}$; $d2 = \text{not } d0 \text{ or } d1$. Ignition of the paper in EN ISO 11925-2 results in a d2 classification. ^h Pass = no ignition of the paper (no classification); Fail = ignition of the paper (d2 classification). ⁱ Under conditions of surface flame attack and, if appropriate to the end-use application of the product, edge flame attack.		



Page 8 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

2 Fire Classification Test on Dino Slatted Composite Cladding

As per the client's requirement, the tested sample was subjected to the following tests.

Sample description: Dino Slatted Composite Cladding

Sample mounting direction: Horizontal

Initial inspection: Not any damage was found

Executive summary:

No.	Test item			Test method	Standard's requirement		Test result	Conclusion
1	Fire growth rate index (<i>FIGRA</i> _{0.4MJ})			EN 13823-2020+A1:2 022	D	≤750 W/s	422W/s	Pass
2	Lateral flame spread (<i>LFS</i>)			EN 13823-2020+A1:2 022		--	< edge of specimen	--
3	Total heat release within 600 s (<i>THR</i> _{600s})			EN 13823-2020+A1:2 022		--	49.9 MJ	--
4	Flammability	Surface flame attack (Exposure = 30 s)	Flame spread within 60s	EN ISO 11925-2-2020		≤150 mm	≤150 mm	Pass
5	Smoke production	Smoke growth rate (<i>SMOGRA</i>)		EN 13823-2020+A1:2 022	s1	<i>SMOGRA</i> ≤30 m ² /s ² <i>TSP</i> _{600s} ≤50 m ²	9.9 m ² /s ²	Class: s2
		Total smoke production within 600 s (<i>TSP</i> _{600s})			s2	<i>SMOGRA</i> ≤180 m ² /s ² <i>TSP</i> _{600s} ≤200 m ²	123.7 m ²	
					s3	Not s1 or s2		



Page 9 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

No.	Test item	Test method	Standard's requirement	Test result	Conclusion
6	Flaming droplets/particles	EN 13823-2020+A1:2022	d0	No flaming droplets/particles within 600 s	Class: d0
			d1	No flaming droplets/particles persisting longer than 10 s within 600 s	
			d2	Not d0 or d1	

Conclusion	EN 13501-1:2018 Fire classification of construction products and building elements - Part 1: Classification using data from reaction to fire tests : D – s2, d0
Remark	1. Test sample is installed on the substrate by screw (test substrates is calcium silicate board, the density of 900 kg/m³ and thickness of 10mm). 2. The test results relate to the behavior of the test specimens of a product under the particular conditions of the test; they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use. 3. This classification report does not represent type approval or certification of the product. The test laboratory has, therefore, play no part in sampling the product for the test, although it holds appropriate references to the manufacturer's factory production control that is aimed to be relevant to the samples tested and that will provide for their traceability.



Page 10 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com


Test Report

Number: GZHH00641273

Tests Conducted

Photo for reference

					
Before the test long wing			Before the test short wing		
					
After testing long wing			After testing short wing		



Page 11 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

Annex A

Classes of reaction to fire performance for construction products excluding floorings and linear pipe thermal insulation products

Class	Test method(s)		Classification criteria	Additional classification
A1	EN ISO 1182 ^a and		$\Delta T \leq 30^{\circ}\text{C}$, and $\Delta m \leq 50\%$, and $t_f = 0$ (i.e. no sustained flaming)	-
	EN ISO 1716		$PCS \leq 2.0\text{MJ/kg}$ ^a and $PCS \leq 2.0\text{MJ/kg}$ ^{b c} and $PCS \leq 1.4\text{MJ/m}^2$ ^d and $PCS \leq 2.0\text{MJ/kg}$ ^e	-
A2	EN ISO 1182 ^a or	and	$\Delta T \leq 50^{\circ}\text{C}$, and $\Delta m \leq 50\%$, and $t_f \leq 20\text{ s}$	-
	EN ISO 1716		$PCS \leq 3.0\text{MJ/kg}$ ^a and $PCS \leq 4.0\text{MJ/m}^2$ ^b and $PCS \leq 4.0\text{MJ/m}^2$ ^d and $PCS \leq 3.0\text{MJ/kg}$ ^e	-
	EN 13823		$FIGRA_{0.2\text{MJ}} \leq 120\text{W/s}$ and $LFS < \text{edge of specimen}$ and $THR_{600\text{s}} \leq 7.5\text{MJ}$	Smoke production ^f and Flaming droplets/particles ^g



Page 12 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00641273

Tests Conducted

Class	Test method(s)	Classification criteria	Additional classification
B	EN 13823 and	$FIGRA_{0.2MJ} \leq 120W/s$ and $LFS < \text{edge of specimen}$ and $THR_{600s} \leq 7.5MJ$	Smoke production ^f and Flaming droplets/particles ^g
	EN ISO 11925-2 ⁱ Exposure =30s	$Fs \leq 150 \text{ mm within } 60 \text{ s}$	
C	EN 13823 and	$FIGRA_{0.4MJ} \leq 250W/s$ and $LFS < \text{edge of specimen}$ and $THR_{600s} \leq 15MJ$	Smoke production ^f and Flaming droplets/particles ^g
	EN ISO 11925-2 ⁱ Exposure=30s	$Fs \leq 150mm \text{ within } 60 \text{ s}$	
Class	Test method(s)	Classification criteria	Additional classification
D	EN 13823 and	$FIGRA_{0.4MJ} \leq 750W/s$	Smoke production ^f and Flaming droplets/particles ^g
	EN ISO 11925-2 ⁱ Exposure=30s	$Fs \leq 150mm \text{ within } 60 \text{ s}$	
E	EN ISO 11925-2 ⁱ Exposure =15s	$Fs \leq 150mm \text{ within } 20 \text{ s}$	flaming droplets/particles ^h
F	No performance determined		



Test Report

Number: GZHH00641273

Tests Conducted

Class	Test method(s)	Classification criteria	Additional classification
	^a For homogeneous products and substantial components of non-homogeneous products. ^b For any external non-substantial component of non-homogeneous products. ^c Alternatively, any external non-substantial component having a $PCS \leq 2,0 \text{ MJ/m}^2$, provided that the product satisfies the following criteria of EN 13823: $FIGRA \leq 20 \text{ W/s}$, and $LFS < \text{edge of specimen}$, and $THR_{600s} \leq 4,0 \text{ MJ}$, and $s1$, and $d0$. ^d For any internal non-substantial component of non-homogeneous products. ^e For the product as a whole. ^f $s1 = SMOGRA \leq 30 \text{ m}^2/\text{s}^2$ and $TSP 600s \leq 50 \text{ m}^2/\text{s}^2$; $s2 = SMOGRA \leq 180 \text{ m}^2/\text{s}^2$ and $TSP 600s \leq 200 \text{ m}^2/\text{s}^2$; $s3 = \text{not } s1 \text{ or } s2$ ^g $d0 = \text{No flaming droplets/ particles in EN 13823 within 600 s}$; $d1 = \text{no flaming droplets/ particles persisting longer than 10 s in EN 13823 within 600 s}$; $d2 = \text{not } d0 \text{ or } d1$. Ignition of the paper in EN ISO 11925-2 results in a d2 classification. ^h Pass = no ignition of the paper (no classification); Fail = ignition of the paper (d2 classification). ⁱ Under conditions of surface flame attack and, if appropriate to the end-use application of the product, edge flame attack.		

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band $w = U$) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



Page 14 of 14

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com

